

FEBRUARY 2011

Remanufactured Instrument Clusters*

**31 NEW
Chrysler SKUs!**

**Ready to Install – Fully Programmed
with Mileage and VIN**
No Vehicle Downtime –
Special Order Ships Same Day



599-501
PT Cruiser, w/o turbo
2005-02
Pop Code: SO
VIO: 358,571

*US Only.

Driveshaft Support Bearing Kit

Supports the Driveshaft at the Center Bearing

934-102
Equinox, Torrent, Vue
2006-02
Pop Code: B
VIO: 713,119



**STORE
STOCK**

Includes U-Joint which
is needed for a
Complete Repair



FAILURE MODE:
• Rubber isolator deteriorates resulting in drivetrain vibration or clunking sound

Shut Off Valve (Emission Valve)

**STORE
STOCK**



Failure Sets
"Check Engine" Light

911-752
Accord
2003-98
Pop Code: B
VIO: 3,110,461

Intake Manifold

Includes Gaskets

**STORE
STOCK**

615-195
Explorer, Ranger
2000-95
(Upper)
Pop Code: B
VIO: 960,363



FAILURE MODE:
• Original unit warps from heat, resulting in port leaks.

Leaf Spring Shackle & Bracket Combo Kits

Leaf Spring Shackles and brackets mount to the frame and hold the Leaf Springs in place



722-100
Ford E Series Vans,
Ford Full Size Trucks
2007-86
Pop Code: D
VIO: 2,394,331



**Complete Repair
Shackle PLUS Bracket
in one Box!**

ALSO NEW

722-101
Ford Full Size Trucks
1997-80
Pop Code: D
VIO: 4,475,352

FAILURE MODE:
• Rust and corrosion
• Failure can cause the Leaf Spring to collapse,
affecting drivability of the vehicle

BE THE FIRST TO KNOW!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

FEBRUARY 2011

LINE UPDATES

Sockets & Pigtails

Pigtails are used to complete the repair by cutting the failed plug and connecting the new Pigtail. Sockets are used with light bulbs and have the same repair procedure



645-628
Low Beam Headlight Pigtail
Astro, Cavalier, Express, Malibu, Safari,
Savana, Silverado, Tahoe, Yukon
2008-95

Pop Code: C
VIO: 16,838,567

- FAILURE MODE:**
- Melting
 - Breaking
 - Damage from impact



645-639
Stop & Tail Lamp Socket

GM 4.3, 8.1L, Engines
2002-96

Pop Code: C
VIO: 799,971

Air Door Actuators



4 NEW SKUs!

604-124
C/K Series
1994-88
Pop Code: D
VIO: 2,651,867

- FAILURE MODE:**
- Motor burnout or electrical failure
 - Failure causes improper function of the A/C, Heat and/ or Defrost

Accelerator Pedal Position Sensor

Monitors and communicates the position of the Pedal to the PCM



699-206
Crown Victoria, Grand
Marquis, Town Car
2008-06

Pop Code: D
VIO: 308,231

- FAILURE MODE:**
- Resistive strip in the sensor wears
 - Sets "Check Engine" light and causes engine to go into "Limp Home" mode

Reduce Repair Cost
Replace Just the Failed Part.
Includes all Components for
a complete repair



Failure Sets
"Check Engine" Light

DIESEL

Vacuum Pump Pulleys

Great Add-on Sale to Vacuum Pumps



300-701
E Series Van,
Ford Full Size Trucks
1992-83 (to 3/92)

Pop Code: D
VIO: 232,363

- FAILURE MODE:**
- Damaged during removal and installation of Vacuum Pump

HHR Handle Replacement Kit

Kit comes complete with Handle, Adhesive, Washers,
Screws and 5/8 Drill Bit



- FAILURE MODE:**
- Weather and/or broken clips

Reduce Repair Cost
Replace the Handle,
Not the Entire Door Panel

80369 [FL/RL]
80370 [FR/RR]
HHR Interior
2010-06

Pop Code: D
VIO: 539,906



View Installation Video
at DormanProducts.com

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492

FEBRUARY 2011

WINDOW REGULATORS

MOST COMPREHENSIVE PROGRAM IN THE AFTERMARKET



749-466 [FL]
749-467 [FR]
3 Series
2010-06


Power Window Regulator w/o Motor
Pop Code: C
VIO: 368,921

NOW OFFERING

1370

TOTAL SKUs

468 Exclusive SKUs



748-619 [FL]
748-620 [FR]
300, Charger, Magnum
2009-05
Window Regulator w/ Motor
Pop Code: C
VIO: 1,898,736

www.DormanProducts.com/GetMore

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492