

APRIL 2011

Differential Yoke

Attaches the Driveshaft to the Differential

697-500
GM Trucks and SUVs
8.5" Ring Gear
2008-82
Pop Code: C
VIO: 14,479,724



FAILURE MODE:

- Yoke seal wears into the yoke causing a groove to form
- Results in differential fluid leaks

Upper Shock Mount

Mounts the Shock Absorbers to the Frame of the Vehicle



924-408
Ranger
2006-83
Pop Code: C
VIO: 5,833,986



FAILURE MODE:
• Rust and Corrosion

Replacement for RUST Prone Parts

DIESEL

Water In Fuel Sensor Also Known As Water Level Sensor

Sensor fits on the Fuel Filter Housing and measures water in fuel levels



904-110
GM Full Size Trucks
2010-01
Pop Code: C
VIO: 723,049

FAILURE MODE:
• Electrical Failure

DIESEL

Turbo Vibration Dampener Also Known As Turbo Resonator

Connects the Turbo Outlet to the Intercooler Hose to absorb turbo whine



904-303
Sprinter
2006-04
Pop Code: C
VIO: 44,083

FAILURE MODE:

- Plastic seam deteriorates and cracks over time
- Results in intake leak, check engine light and limp home mode



Sway Bar Kit



927-106
Bravada 2004,
Envoy, Rainier
2007-04
Pop Code: C
VIO: 1,106,276

Replacement for RUST Prone Parts

2 NEW SKUs!

Original Tubular Design

Corrosion Leads to Ends Splitting and Eventually Breaking



Solid Forged Design Eliminates Possibility of Ends Breaking



BE THE FIRST TO KNOW!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

APRIL 2011

LINE UPDATES

Ignition Lock Cylinder

Tumblers allow for the use of the Original Key, eliminating the need for reprogramming



924-709
Aspen, Dakota, Durango,
Raider, Ram Pickup
2008-01
Pop Code: C
VIO: 3,377,115

Exhaust Bracket

Keeps Exhaust System level in relation to the body of the vehicle



917-027
Maxima
1994-89
Pop Code: C
VIO: 230,725

FAILURE MODE:
• Cracks due to excessive vibration and rust

Replacement for
RUST Prone Parts

Harmonic Balancers

2 NEW SKUs!

594-326
Sprinter
2006-03
Pop Code: D
VIO: 58,803



FAILURE MODE:
• Rubber deteriorates due to heat
• Failure can cause engine damage

Wheel Hubs (Flanges)

Includes axle nut & wheel stud (where applicable)

Replacement for
RUST Prone Parts

930-415
GS 2005-93,
SC 2009-92,
Supra 1998-94
Pop Code: D
VIO: 618,966



FAILURE MODE:
• Bearing Race seizes itself to the Hub, preventing re-use

Hazard Switches

Failure Renders Turn Signals and Flashers Inoperative



924-608
Bravada 2001-98,
S10, Sonoma 2004-98
Pop Code: C
VIO: 2,100,969

Air Door Actuators

4 NEW SKUs!



604-123
MGM 3.8, 4.9, 5.0,
5.7L
1999-92
Pop Code: D
VIO: 2,005,318

BE THE FIRST TO KNOW!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

APRIL 2011


WINDOW REGULATORS

MOST COMPREHENSIVE PROGRAM IN THE AFTERMARKET

382 Exclusive SKUs

NOW OFFERING
1390
TOTAL SKUs

749-192 [FL]
749-193 [FR]
Grand Cherokee
2005
Power Window Regulator w/ Motor
Pop Code: D
VIO: 353,338



749-556 [RL]
Ford Full Size Trucks
2002-97
Power Window Regulator w/o Motor
Pop Code: C
VIO: 1,012,075



748-532 [FL]
748-533 [FR]
Malibu
2008-04
Power Window Regulator w/ Motor
Pop Code: D
VIO: 1,0312,454

Visit www.DormanProducts.com/GetMore
for Product Information, Installation Sheets, Product Videos and More!

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492