

**MAY 2011**

## Remanufactured Climate Control Modules



View Video at  
DormanGuide.com



**Plug & Play Design**  
for easy installation  
(No Programming Required)

**FAILURE MODE:**

- Mode selection fails
- Loses ability to switch airflow, defaults to defrost

**599-009**

Avalanche, Escalade,  
Sierra, Silverado,  
Suburban, Tahoe, Yukon  
2004-03

**Pop Code: C**  
**VIO: 2,632,683**

**ALSO NEW**

**599-013**

Avalanche, Escalade,  
Sierra, Silverado, Suburban,  
Tahoe, Yukon  
2007-05

**Pop Code: D**  
**VIO: 3,391,744**

## Upper Shock Mount Kits

Mounts the shock absorber to the frame of the vehicle

Replacement  
for **RUST**  
Prone Parts



**COMPLETE KIT**

Includes Hardware  
for Complete Repair

**924-403 [RR]**  
**924-404 [RL]**  
C/K Pickup  
2000-88

**Pop Code: C**  
**VIO: 1,961,397**

**FAILURE MODE:**

- Rust and Corrosion

## Intake Coupling Kit

Couples the Throttle Body to the Intake Manifold

**COMPLETE KIT**

Includes Intake Manifold  
Gaskets for a Complete Repair

**911-010**  
Aurora, Bonneville, Deville  
2005-00

**Pop Code: C**  
**VIO: 571,737**

**FAILURE SETS**  
"Check Engine" Light



**FAILURE MODE:**

- Rubber Boots deteriorate over time
- Results in intake leaks and drivability issues

## 4WD Vacuum Solenoids Also Known As Emission Solenoids

Controls engagement of 4WD front Hubs



**600-400**  
Expedition, Explorer,  
F-Series Pickup  
2009-95

**Pop Code: C**  
**VIO: 7,154,704**

**ALSO NEW**

**600-401**  
Expedition, Explorer,  
F-Series Pickup  
2004-95

**Pop Code: D**  
**VIO: 4,362,966**

- FAILURE MODE:**
- Grit or water intrusion

## DIESEL

## High Pressure Fuel Sensor

Measures fuel pressure in the Fuel Rail

**904-309**  
Ram Pickup  
2007-03

**Pop Code: D**  
**VIO: 390,163**



**FAILURE MODE:**

- Sensor failure
- Results in limp run mode

**FAILURE SETS**  
"Check Engine" Light

**BE THE FIRST TO KNOW!**  
Sign Up at [www.DormanProducts.com/Signup](http://www.DormanProducts.com/Signup)

**Customer Service:**  
**1-800-523-2492**

**MAY 2011**

**Remanufactured Instrument Clusters\***

**Ready to Install – Fully Programmed  
with Mileage and VIN**  
No Vehicle Downtime –  
Special Order Ships to Store Same Day

**5 NEW SKUs!**

**599-326**  
Buick Regal/Century  
2004-99  
**Pop Code: SO**  
**VIO: 728,543**



\*US Only.

**Vent Window Motor**

Controls pivoting rear windows on minivans and sport utility vehicles



**948-100 [LH]**  
**948-101 [RH]**  
Montana, Relay, Silhouette, Terraza  
2008-98  
**Pop Code: D**  
**VIO: 1,180,937**

**ALSO NEW**

**948-500 [LH]**  
**948-501 [RH]**  
Odyssey  
2004-99  
**Pop Code: D**  
**VIO: 657,993**

**FAILURE MODE:**

- Motor burnout, electrical failure or water intrusion
- Window becomes stuck in one position

**Exhaust Manifold Hardware Kits**

Attaches Manifold to the Cylinder Head



**674-001**  
Accord, Civic  
1999-84  
**Pop Code: C**  
**VIO: 2,159,360**

**ALSO NEW**

**674-003**  
Celica  
1995-90  
**Pop Code: D**  
**VIO: 622,367**

**FAILURE MODE:**

- Corrosion, breakage

**LINE UPDATES**

**Harmonic Balancers**

**5 New SKUs!**

**594-311**  
Ford 4.6L  
2010-01  
**Pop Code: B**  
**VIO: 2,775,054**



**FAILURE MODE:**

- Rubber deteriorates due to heat
- Failure can cause engine damage

**Window Regulators**

The Most Comprehensive Program in the Aftermarket

**382 Exclusives!**

**741-003 [FL]**  
**741-004 [FR]**  
Forester  
2008-03  
Power Window  
Regulator  
**Pop Code: C**  
**VIO: 531,868**



Visit [www.DormanProducts.com/GetMore](http://www.DormanProducts.com/GetMore)  
for Product Information, Installation Sheets, Product Videos and More!

**BE THE FIRST TO KNOW!**  
Sign Up at [www.DormanProducts.com/Signup](http://www.DormanProducts.com/Signup)

**Customer Service:**  
**1-800-523-2492**