

DORMAN®
NEW SINCE 1918

**NEW TO THE
AFTERMARKET**
THINK IT'S DEALER ONLY? THINK DORMAN.



599-304*
Trailblazer 2004-02
(Without Driver Information Center)

Instrument Clusters
Fully Remanufactured

*No Vehicle Downtime:
Special Order Ships Same Day,
Fully Programmed with
Mileage & VIN*

**US Models Only*

Brake Backing Plates

Dorman Engineered
Split Design of 924-002
Saves Labor, No Need to
Remove the Axle

RUST

924-213

GM Full Size Trucks 2007-00;
Express, Savana 2009-03



Steering Knuckles



Dorman Engineered
Material Upgraded from
Aluminum to Cast Iron
to Resist Damage

697-910 FR
697-911 FL
FWD
GM 2010-97

Throttle Position Sensors



911-753
Accord, Civic, CR-V, CRX,
Del Sol, Integra,
Prelude 2001-88

Reduce Repair Cost
Replace Just the Failed Part

Vacuum Switching Valves

Failure Sets "Check Engine" Light



911-601
4Runner, Avalon, Camry,
Celica, Corolla, ES, 300,
Matrix, Solara 2008-99

Also Available:
ES330, MR2, RAV4, Tacoma, Tundra

Thermostat Housing



902-204
Explorer 4.0L
2001-97

**Exhaust Manifold
Crossover Pipe Kits**



679-000
Chrysler Minivans
2000-96

Includes
Gaskets
& Hardware

Air Door Actuators



604-209
Expedition, Explorer,
Mountaineer 2010-02;
Manual A/C